



Movement of oil within marsh. Background photo from 2/6/07 (day 16 of the incident) shows oil in a small pool. A wind shift later in the day resulted in oil migrating across the channel and stranding on the other shoreline, as documented by the inset photograph from next morning's overflight. The entire marsh is surrounded by booms, but oil can move within the marsh.