

M/V Kuroshima Incident

Pictorial view of cleanup operations

Date: 4/21/98



Decon station



High-pressure wash along NE lake shoreline



Divers doing SCAT assessment of area in front of bridge



Shoreline cleanup operations along E shoreline



Shoreline cleanup operations along SE portion of lake